

Release Note

General information	
Issue ID Number	1-GJDLN
Product Name	Fiery X3e 50C-K Color Server v1.1 EFIGS
Issue Date	January 25, 2005

Files included in this release	
File name	File size
1-GJDLN.ps	10.1 Megabytes
ICC.zip	4.4 Megabytes
Relnotes.pdf	

Issue description	
New profiles for optimal color output for an engine with new toner.	
Steps to reproduce	
NA	
Resolution type:	Closed - Patch

Resolution	
1-GJDLN.zip	

Important notes	
Installation Steps: <ol style="list-style-type: none">1. Download/Import the patch file “1-GJDLN.ps” with either Fiery Downloader or Command Workstation to the “Direct” queue.2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.3. The system must be rebooted twice for the patch to be effective using the following steps.4. Please select “Shut Down” and then “Reboot System” on the Fiery LCD. When the Fiery has come to “Idle”, repeat the steps to reboot the system.5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page. <p>Verify the Update Info section. It should contain the patch number “1-GJDLN”.</p> <p>The matching ICC profile is also released with this patch. Please unzip it onto a client computer and point to this folder when you need to use it.</p>	

Known Issues	
NA	