



Laser cutter requires at least 2 x double sockets.

CAD PC requires 1 x double socket

Small machines, shapeoko, lathe, drill need 3 x double sockets