

power UDB and RX only by disconnecting
 RX/UDB power cable from failsafe
 and supplying 5-12V power directly to UDB input channel
 The failsafe mux is then unpowered and
 RX is powered through PWM input cable

