





UnderSampling Test

Setup PowerSDR : freq 23.528MHz (\Rightarrow 50.200MHz), LSB, DriveLevel 100, Tune mode
 firmware : modified 20151018 (Interpolation OFF)

1. No Filter



2. through Diplexer (B.P.F.)



need to reduce more 23.528MHz carrier and spur.

